





Surveyor: Zaw La

Date Visited: 19.8.2015

Time Visited: 15:00to 16:30

Weather Condition: sunny

The last time of heavy raining: - yesterday

| No | Item | Condition | Description and Photos |
|----|-------------------------|---|---|
| 1 | Condition of - | | |
| | (1). Well | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | Description & Photos: -See ANNEX.1 - Although both of the two wells are dirty with outside water last week, well no. 1 is gradually clean this week and surrounding people are using it again. In terms of avoiding outside water, both wells need to be renovated again in summer. The buffer of some hand pumps need to be changed, but people get water from their owned well of rain water currently. |
| | (2). <u>Drainage</u> | Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i> | <u>Description</u> -Water level in the drainage canals lower than last week because there was only a little rain last night. But, the stream along the drainage canal may needs to be rehabilitated in next summer. <u>Photos</u> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;"> <p>Near Well No. 1</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near HH No. 48</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near HH No. 1</p>  </div> <div style="width: 50%; text-align: center;"> <p>Near garbage pit</p>  </div> </div> |

| | | | |
|------------------------|---|---|--|
| | | | <p>In front of HH No. 1</p>  |
| (3). Road | <p>Improved <input type="checkbox"/></p> <p>Same <input checked="" type="checkbox"/>*</p> <p>Worse <input type="checkbox"/></p> <p><i>*as last week</i></p> | <p><u>Description</u></p> <p>- The roads are being wet a bit and muddy in some areas but no problem for walking.</p> <p><u>Photos</u></p> | <p>Front main road</p>  <p>The right road of relocation site</p>  <p>Middle road</p>  <p>The left road of relocation site</p>  |
| (4). Garbage Condition | <p>Improved <input type="checkbox"/></p> <p>Same <input checked="" type="checkbox"/>*</p> <p>Worse <input type="checkbox"/></p> | <p><u>Description</u></p> <p>-Garbage pit is used by people.</p> <p>-Garbage pit is cleaned and a new access way to garbage pit had been constructed.</p> <p>-There is no problem for smell at the garbage pit so far.</p> <p>-People throw garbage at the backside of Third Row and it need to be collected.</p> | |



No
1

Item
(5). Fly
proof
toilet

Condition
Improved

Same *
Worse
*as last
week

Description

-All of fly proof toilets are used by people.

| Condition | No. of HHs | |
|-----------|---------------------|-------------------------|
| | This week condition | Previous week condition |
| Level 1 | 6 | 6 |
| Level 2 | 18 | 18 |
| Level 3 | 29 | 29 |
| Level 4 | 13 | 13 |
| No Toilet | 2 | 2 |

<Evaluation Criteria>

Level 1

- No need to repair fly proof toilet
- No/rarely toilet unavailable

Level 2

- Need to repair fly proof toilet
- Rarely toilet unavailable

Level 3

- Need to repair fly proof toilet
- Often toilet unavailable
- As the result of filling the soil and also raining, some toilets are inconvenience to use.

Level 4

- Need to repair urgently fly proof toilet
- Often toilet unavailable
- After filling the soil, some toilets need to be lifted up.




(6).
Electricity


Improved
 Same *
 Worse
 *as last week

Description

- Electricity comes regularly.
- Electric poles and transformer are supported in good foundation.
- But, there is a hole at an electric pole which was hit by a truck car. The electric pole needs to be renovated.

Photos



| No | Item | Condition | Description and Photos | | | | | | | | | | | | | | | | | |
|-----------|---|---|---|-----------|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|----|----|---------|---|---|
| 2 | House Construction | No. of houses not completed (2) | <p><u>Description</u> -HH No.5, the construction for kitchen, toilet and water tank seems to be started again.</p>  | | | | | | | | | | | | | | | | | |
| 3 | Living Status of PAPs (Sold house, renting, etc.) | <p><u>Description</u></p> <p>(1) House ownership (1)-1 No. of house that are owned by PAPs (50) (1)-2 No. of house that were sold (18)</p> <p>(2) Living condition (2)-1 No. of houses where PAPs live (41) (2)-2 No. of houses where not original PAPs lives (22) (2)-3 No. of houses where nobody lives (5)</p> <p>Location Map: See ANNEX.2</p> | | | | | | | | | | | | | | | | | | |
| 4 | Other issue | | <p>(1). Drainage condition for rain water in their compounds</p> <p><u>Description</u> -Rainy season has been started. -Most of the compounds are wet.</p> <table border="1" data-bbox="367 1073 948 1331"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>14</td> <td>14</td> </tr> <tr> <td>Level 2</td> <td>30</td> <td>30</td> </tr> <tr> <td>Level 3</td> <td>20</td> <td>20</td> </tr> <tr> <td>Level 4</td> <td>4</td> <td>4</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1 -No mud and no standing water with their own drainage system in their compound</p> <p>Level 2 -No mud and no standing water in their compound</p> <p>Level 3 - Some or little mud and standing water in their compound</p> <p>Level 4 -A lot of mud and standing water in their compound</p> | Condition | No. of HHs | | This week condition | Previous week condition | Level 1 | 14 | 14 | Level 2 | 30 | 30 | Level 3 | 20 | 20 | Level 4 | 4 | 4 |
| Condition | No. of HHs | | | | | | | | | | | | | | | | | | | |
| | This week condition | Previous week condition | | | | | | | | | | | | | | | | | | |
| Level 1 | 14 | 14 | | | | | | | | | | | | | | | | | | |
| Level 2 | 30 | 30 | | | | | | | | | | | | | | | | | | |
| Level 3 | 20 | 20 | | | | | | | | | | | | | | | | | | |
| Level 4 | 4 | 4 | | | | | | | | | | | | | | | | | | |

Photos




4 (2) Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

| Type | No. of HHs | Remarks |
|--------------|------------|--|
| Shady tree | 12 | Albizia, Indian almond, etc. HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65 |
| Fruit tree | 24 | Banana, Mango, sugarcane, coconut, citrus, etc. HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65 |
| Vegetable | 10 | Spices, peas, roselle, etc. HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63 |
| Floral plant | 20 | Many species. HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65 |





4 (3) Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

| Type | No. of HHs | Remarks |
|-------------------|------------|--|
| Cow | 5 | HH No. 3, 18, 42, 47 and 54 |
| Pig | - | - |
| Goat | 1 | HH.47 |
| Chicken and ducks | 15 | HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62 |

Photos



ANNEX.1

As of 19.8.2015

Water is clean and people nearby are using it for drinking and living use. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with thick one for the better use.



This hand pump is not functioned very well and need to change the buffer . Currently the PAP use the well and rain water instead of this hand pump.

This hand pump is functioned very well. Water is clean and everyone nearby using this hand pump for drinking water and living use.

Hand pump isn't functioned.

This well cannot be used as water is dirty. A pulley wheel, bucket and a rope have been set up but the rope seems to be thin and it is better to be changed with a thick one for the better use.








The buffer of the hand pump needs to be change. Therefore, people living nearby are using water from their owned pump or rain water at the moment.



This hand pump is functioned very well. Water is clean and everyone living nearby is using this hand pump. Moreover water filter tank for remove the smell of iron has been set up beside the hand pump. There is no smell of iron and people enjoy water for drinking and living use.



-  Closed Well
-  New Well (Hand pump)
-  Open Well
-  Hand Pump
-  Private Well

