

Weekly Field Report

No. 11


Surveyor: Sithu Nyein

Date Visited: 03.11.2014







Time Visited: 9:30 to 11:00


Weather Condition: Sunny

The last time of heavy raining: one day ago

| No | Item                        | Condition   | Description and Photos   |
|----|-----------------------------|---|--|
| 1  | Condition of -<br>(1). Well | Improved <input type="checkbox"/><br>Same <input type="checkbox"/><br>Worse <input checked="" type="checkbox"/>                         | Description & Photos:<br>-See ANNEX.1<br>-Hand Pump of Well No. 9, 10 and 11 are needed to repair.<br>-Hand Pump of Well No.6 has been repaired by people who live nearby.                       |
|    | (2). Drainage               | Improved <input type="checkbox"/><br>Same <input checked="" type="checkbox"/><br>Worse <input type="checkbox"/><br><i>*as last week</i> | <p><u>Description</u><br/>-Water level in the drainage canal is near to the bottom.</p> <p><u>Photos</u></p>  |
|    | (3). Road                   | Improved <input type="checkbox"/><br>Same <input checked="" type="checkbox"/><br>Worse <input type="checkbox"/><br><i>*as last week</i> | <p><u>Description</u><br/>-The roads are almost dry and no problem for traffic as a whole.</p>   |

|                        |  |   |   |
|------------------------|--|---|---|
|                        |  |   | <p><u>Photos</u></p>  |
| (4). Garbage Condition | <p>Improved <input checked="" type="checkbox"/></p> <p>Same <input type="checkbox"/></p> <p>Worse <input type="checkbox"/></p> | <p><u>Description</u></p> <ul style="list-style-type: none"> <li>-Garbage pit is used by people.</li> <li>-Garbage has been collected by Kyauk Tan Municipal Department on 31<sup>st</sup> Oct, 2014.</li> <li>-Garbage pit is almost empty.</li> </ul> |                     |

| No        | Item                  | Condition   | Description and Photos  |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
|-----------|-----------------------|---|---|-----------|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|---|---|---------|---|---|-----------|---|---|
| 1         | (5). Fly proof toilet | Improved <input type="checkbox"/><br>Same <input checked="" type="checkbox"/><br>Worse <input type="checkbox"/><br><i>*as last week</i> | <p><u>Description</u><br/>-All of fly proof toilets are being used by people.</p> <table border="1"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>42</td> <td>42</td> </tr> <tr> <td>Level 2</td> <td>21</td> <td>21</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>5</td> <td>5</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b><br/> <b>Level 1</b><br/>           -No need to repair fly proof toilet<br/>           -No/rarely toilet unavailable<br/> <b>Level 2</b><br/>           -Need to repair fly proof toilet<br/>           -Rarely toilet unavailable<br/> <b>Level 3</b><br/>           -Need to repair fly proof toilet<br/>           -Often toilet unavailable<br/> <b>Level 4</b><br/>           -Need to repair urgently fly proof toilet<br/>           -Often toilet unavailable</p> <p><u>Photos</u></p>    | Condition | No. of HHs |  | This week condition | Previous week condition | Level 1 | 42 | 42 | Level 2 | 21 | 21 | Level 3 | 0 | 0 | Level 4 | 0 | 0 | No Toilet | 5 | 5 |
| Condition | No. of HHs            |   |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
|           | This week condition   | Previous week condition   |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
| Level 1   | 42                    | 42  |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
| Level 2   | 21                    | 21  |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
| Level 3   | 0                     | 0   |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
| Level 4   | 0                     | 0   |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
| No Toilet | 5                     | 5   |   |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |
|           | (6). Electricity      | Improved <input type="checkbox"/><br>Same <input checked="" type="checkbox"/><br>Worse <input type="checkbox"/><br><i>*as last week</i> | <p><u>Description</u><br/>-Electricity is coming regularly<br/>-Electric poles and transformer are supported in good foundation.</p> <p><u>Photos</u></p>      |           |            |  |                     |                         |         |    |    |         |    |    |         |   |   |         |   |   |           |   |   |

| No        | Item  | Condition  | Description and Photos  |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
|-----------|---|--|---|------------|--|---------------------|-------------------------|---------|----|----|---------|----|----|---------|----|----|---------|----|----|--|
| 2         | House Construction  | No. of houses not completed (2)  | <p><u>Description</u><br/>-HH No.1 doesn't have ladder and nobody is living<br/>-In HH No.5, the construction for kitchen, toilet and water tank seems stopped. Nobody lives.</p> <p><u>Photos</u></p>  |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
| 3         | Living Status of PAPs (Sold house, renting, etc.)         | <p><u>Description</u><br/>(1) House ownership<br/> (1)-1 No. of house that are owned by PAPs (49)<br/> (1)-2 No. of house that were sold (19)<br/> (2) Living condition<br/> (2)-1 No. of houses where PAPs live (38)<br/> (2)-2 No. of houses where not original PAPs lives (26)<br/> (2)-3 No. of houses where nobody lives (4)<br/> Yellow= Changes from previous week</p>  | <p>Location Map: See ANNEX.2</p>  |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
| 4         | Other issues  |  |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
|           | (1). Drainage condition for rain water in their compounds | <p><u>Description</u><br/>-Because of heavy rain, there are puddles and muddy area in some compounds.</p> <table border="1" data-bbox="400 1323 987 1563"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>12</td> <td>12</td> </tr> <tr> <td>Level 2</td> <td>26</td> <td>27</td> </tr> <tr> <td>Level 3</td> <td>18</td> <td>18</td> </tr> <tr> <td>Level 4</td> <td>12</td> <td>11</td> </tr> </tbody> </table> <p><b>&lt;Evaluation Criteria&gt;</b><br/> <b>Level 1</b><br/> -No mud and no standing water with their own drainage system in their compound<br/> <b>Level 2</b><br/> -No mud and no standing water in their compound<br/> <b>Level 3</b><br/> - Some or little mud and standing water in their compound<br/> <b>Level 4</b><br/> -A lot of mud and standing water in their compound</p> | Condition   | No. of HHs |  | This week condition | Previous week condition | Level 1 | 12 | 12 | Level 2 | 26 | 27 | Level 3 | 18 | 18 | Level 4 | 12 | 11 |  |
| Condition | No. of HHs  |  |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
|           | This week condition                                       | Previous week condition  |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
| Level 1   | 12  | 12   |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
| Level 2   | 26  | 27   |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
| Level 3   | 18  | 18   |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |
| Level 4   | 12  | 11   |   |            |  |                     |                         |         |    |    |         |    |    |         |    |    |         |    |    |  |



4 (2)  
Plantation

Description

-In front of their compounds, they planted shady trees, fruit trees, vegetables and floral plants.

| Type         | No. of HHs | Remarks  |
|--------------|------------|--|
| Shady tree   | 12         | Albizzia, Indian almond, etc.<br>HH No. 2, 3, 14, 19, 20, 21, 25, 27, 29, 32, 41 and 65  |
| Fruit tree   | 24         | Banana, Mango, sugarcane, coconut, citrus, etc.<br>HH No. 2, 3, 4, 7, 8, 9, 11, 17, 21,24, 25, 27, 33, 37, 38, 39, 41, 43, 45, 46, 47, 48, 54 and 65 |
| Vegetable    | 10         | Spices, peas, roselle, etc.<br>HH No. 22, 23, 25, 27, 38, 39, 40, 42,45 and 63   |
| Floral plant | 20         | Many species.<br>HH No. 2, 9, 14, 15, 17,21, 23, 27, 32, 33, 38, 39, 40, 41, 42, 43, 47, 48, 58 and 65   |

Photos





HH No. 40



HH No. 15

4 (3) Livestock

Description

-They are raising chicken, ducks, goats, pigs and cows.  
 -Even though they have cows, they do not keep their cows in relocation site instead they keep in their farms or other places.

| Type              | No. of HHs | Remarks  |
|-------------------|------------|--|
| Cow               | 5          | HH No. 3, 18, 42, 47 and 54  |
| Pig               | 1          | HH No. 2   |
| Goat              | 2          | HH No. 50 and 51   |
| Chicken and ducks | 15         | HH No. 4, 8, 12, 14, 28, 30, 32, 41, 47, 50, 51, 52, 55, 56 and 62 |

Photos



5 **Remarks**

- The garbage in the garbage pit has been collected by Kyauk Tan Municipal Department on 31<sup>st</sup> Oct, 2014.
- The renter from HH No.61 who works sewing bussiness moved to HH No.10. In HH No.61, nobody lives now.

